



TYPES OF WEAR


ABRASION BY TEARING



LOW PRESSURE ABRASION



HIGH PRESSURE ABRASION



- F** Load to be applied: N
- S** Oscillation of trajectory: Length
- V** Speed of movement: m/min
- D** Duration: hours
- T** Temperature °C

Abrasion tests complying with standards (ASTM G 75)

There are different ways of testing to determine the products resistance to abrasion.

The ASTM G 75 standard can be an option

